Work Order ID 64294 Wednesday, December 01, 2010 1:22:43 PM									Page 1
Item ID: D3838-041 Revision ID:		Accept				Setup	Start		
Item Name: Rib Assembly (Basket Lid, LH)	· .						Stop		
Start Date: 12/1/2010 Start Qty: 2.00 Required Date: 12/8/2010 Req'd Qty: 2.00 Reference:		•	Cust Item I	ID:		·		, <b></b>	
Approvals: Process Plan: QC:	Date: <u>/()-/]-/</u>	Tooling: SPC (Y/N):		ate:		Run	Start Stop		
Sequence ID/ Operation Work Center ID Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Acco	ept Re		Reject Number	Insp. Stamp
Draw Nbr Revision Nbr									
D3838 Rev A									
Large Fab  Large Fab  Large Fab  Large Fab  1- cut D38	338-1 and D3838-3 rib as pe	0.00 0.00					- mar .uma		
	identification markings	a dwg D3636				•			
3- deburr			SAD	10-12	-07				
to finish s A/R ER  5- c'sink h  6- grind w  7- weld D	3838-1 to D3838-3 and drill ize as per dwg D3838 (316 S.S. Rod Batch: 11 cole as per dwg reld flush where indicated or 3759-1 bushing as per dwg R316 S.S. Rod Batch: 11	<b>585</b> 1 dwg D3838  D3838	0	10.10					

8- grind bushing weld flush as per dwg dwg D3838

9- deburr hole if necessary

	•								
W/O:			W	ORK ORDER CHANG	GES				Ŧ
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								-	
									į
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date: _	
	Re	solution:	Disposition	on:	QA: N/C C	losed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NC	R)			
DATE	CTED	Description of NC	Initial	ction B	Verifi	cation	Approval	Approval	
DATE	SIEP	STEP Description of NC Section A		Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector
		A							
								ļ	
		***	•	<u> </u>					
						,			

Wednesday, December 01, 2010 1:22:43 PM

Item ID:

D3838-041

Accept



Setup Start

Stop

Revision ID:

Item Name:

Rib Assembly (Basket Lid, LH)

**Start Date:** 

Start Qty: 2.00 12/1/2010

Req'd Qty: 2.00

Operation

Description

**Cust Item ID: Customer:** 

Reference:

**Approvals:** 

Process Plan:

Date:

Tooling:

Date:

Run

Start

Stop



Required Date: 12/8/2010

Date:

SPC (Y/N):

Set Up/

Date:

Reject

Reject

Insp.

Sequence ID/ Work Center ID

130

Quality Control

Memo

Memo

Memo

**Run Hours** 

0.00

Tool ID

Tool # Plan Code

Accept Qty Qty

Number Stamp

0.00

140



Quality Control

QC5- Inspect part completeness to step on W/O

QC9- Inspect visual per QSI004- Fusion Welds

150



Packaging

Identify as per dwg & Stock Location:

0.00

0.00

10-12-03

W/O:	•		\/\/	ORK ORDER CHAN	GES							
DATE	STEP	PRO	OCEDURE CH		dL3	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No	:	PAR #:	Fault Cate	egory:	NCF	R: Yes	No <b>DQ</b>	A:	Date:			
				Disposition: QA: N/C Closed:								
NCR:		1	WORK ORD	ER NON-CONFORM	JANCE	(NCR	)					
DATE	STEP	Description of NC Section A	Initial Chief Eng	Section B ption Sign & Date			cation ion C	Approval Chief Eng	Approval QC Inspector			
			Office Ling	Chief Eng								
							-			-		
					•							
	1				•							

#### Work Order ID 64294

Wednesday, December 01, 2010 1:22:43 PM



Page 3

Item ID:

D3838-041

Accept

Setup Start



**Revision ID:** 

Item Name:

Rib Assembly (Basket Lid, LH)

**Start Date:** 12/1/2010 Start Qty: 2.00

Req'd Qty: 2.00 Required Date: 12/8/2010

**Cust Item ID: Customer:** 

Tool ID

Reference:

Δ	nn	rov	za l	e •
A	DĐ	ΓU	v a i	Si

Process Plan:

Date:

Date: Tooling:

SPC (Y/N):

Date: Date:

Tool # Plan

Code

Run

Accept

1 4

Qty

Start

Reject

Qty

Stop



Sequence ID/

**Work Center ID** 

QC:

Operation Description

QC21- Final Inspection - Work Order Release

Set Up/ **Run Hours** 

0.00

Number Stamp

Reject

160

Memo

0.00

Quality Control

JUE - 08

Insp.

W/O:			WC	ORK ORDER CHANGE	S		· · · · · · · · · · · · · · · · · · ·		,			
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No	):	PAR #:	Fault Cate	gory:	NCR: Yes No DQA: Date:							
	Re	esolution:	Dispositio	n:	QA: N/C C	losed:		Date: _				
NCR:		,	WORK ORD	ER NON-CONFORMAN	NCE (NCI	7)						
DATE	STEP	Description of NC		Corrective Action Section			cation	Approval	Approval			
DATE	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector			
							•					
					-							
•												

# **Picklist Print**

Wednesday, December 01, 2010 1:22:47 PM

Work Order ID: 64294

Parent Item:

D3838-041

Parent Item Name: Rib Assembly (Basket Lid, LH)



Start Jate: 12/1/2010

Required 5 ate: 12/8/2010

Page 1

Start Qty: 2.00


Required Qty: 2.00

C	•	m	m	^	n	40	٠
٠.	v		111		11	1.5	


IPP Rev:A 08-12-01 new issue DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
03759-1 		Manufactured	No				Each	23.0000	1	Epl.	16.1	2.07	2
				Location	!	Loc C	<u>Otv</u>	Loc Code		<b>/</b>			
				ST084	•		3		_		_		
					56942		3		_		_		
				WA			20		_		_		
					54072		9		-	7/2	<b>47</b>		
M204TCÓ 750W 066			3.7		6387	100	11	1 0 60 0 50		B631		-	
		Purchased	No			100	f	1,062.852	1.0317	2.172 <b>SA</b>	)/	0-12	-67
304 SQ Tube .75x.75x.065\	V			Location	<u>.</u>	Loc	Qty	Loc Code			,		
				MAT		1015.74							
					112398		0		_		_		
					115494	4.4	4725				_		
					115593	11.2			_		_		
					116267		1000		-				
				WA	115274	47.10			_		_		
							2185						


		<del></del>											
W/O:			WO	RK ORDER CHANGE	S		<del></del>						
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
			•										
								·					
Part No	):	PAR #:	Fault Category: NC			NCR: Yes No DQA: Date:							
	R	esolution:	Disposition		QA: N/C Clo	osed:		Date: _					
NCR:			WORK ORDE	R NON-CONFORMAN	NCE (NCR	)							
DATE	STEP	Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval				
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date			Chief Eng	QC Inspector				
						·			reference and and the				
								1					



		·								
W/O:			WO	RK ORDER CHAN	GES					•
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Categ	jory:	NC	R: Yes	No <b>DQ</b>	A:	Date: _	
	Res	olution:	Disposition	1:	QA	: N/C CI	osed:		Date:	
NCR:			WORK ORDE	R NON-CONFORM	<b>IANCE</b>	(NCR	3)			
	OTED	Description of NC			ection B	r	Verifi	cation	Approval	Approval
DATE	STEP Description of NC Section A		Initial Action Des Chief Eng Chief E		1	Sign & Date	Section C		Chief Eng	QC Inspector
						ļ				
		•				<u>.</u>			1	
									į	
				-A						



Duit Moi	oopaco									***	
W/O:			WORK ORDER CHANGES								
DATE	STEP	PRO	CEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
			· · · · · · · · · · · · · · · · · · ·			<u></u>					
Part No	:	PAR #:	Fault Category: NCR: Yes No D				No <b>DQ</b>	DQA: Date:			
	R	esolution:	Dispositio	on:	QA:	N/C Cld	osed:		Date:	<i>!</i> '	
NCR:		V	WORK ORD	ER NON-CONFORM	ANCE	(NCR	) .				
DATE	CTED	Description of NC			tion B	0: 0		cation	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Sect	ion C	Chief Eng	QC Inspector	
				·							
									5		
						_					
								-			



<b>-</b> 4	. oopaoo								
W/O:			W	ORK ORDER CHANGE	:S				• •
DATE	STEP	PROC	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		. *							
Part No	):	PAR #:	_ Fault Cate	egory:	NCR: Yes	No <b>DQ</b>	<b>A</b> :	Date: _	
	R	esolution:	_ Disposition	on:	QA: N/C CI	osed:		Date: _	
NCR:		W	ORK ORE	DER NON-CONFORMA	NCE (NCF	R)			
DATE	STEP	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval
	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		on C	Chief Eng	QC Inspector
									1
		•							
		·							